

WINDOW ASSEMBLY
Margaretha H. Wirawan
Appl. No.: 10/645,984 Atty Docket: WIRM.001A
Replacement Drawings

1/28





FIG. 1

2/28



3/28




FIG. 3

FIG. 4

FIG. 5

4/ 20






FIG. 8

FIG. 7

FIG. 6




FIG. 9

FIG. 10

FIG. 11

6/28




FIG. 12 FIG. 13

7/28




FIG. 15




FIG. 14

8/28




FIG. 17




FIG. 16






FIG. 18 FIG. 19

WINDOW ASSEMBLY
Margaretha H. Wirawan
Appl. No.: 10/645,984 Atty Docket: WIRM.001A
Replacement Drawings

10/28



11/28




FIG. 23




FIG. 22

12/28




FIG. 25




FIG. 24

13/28




FIG. 26




FIG. 28




FIG. 27

15/28




FIG. 30





FIG. 29






FIG. 34




FIG. 33




FIG. 35

19 / 28




FIG. 36

FIG. 37




FIG. 39




FIG. 38




FIG. 40

FIG. 41

22/28




FIG. 42

23/28




FIG. 44




FIG. 43

24/28




FIG. 46




FIG. 45

25/28




FIG. 48




FIG. 47

26/28




FIG. 49

27 / 28




FIG. 50

28/28




FIG. 51